



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
September 9, 2005

Supervisor 1027

Mine Name: Midvale-Placer
Operator Name: Mark Dotson
1208 S 200 W
PO Box 492
Milford, Utah 84751
Inspector(s): Tom Munson
Other Participants: Mark Dotson
Mine Status: Never activated

Permit number: S010060
Inspection Date: 8/30/2005
Time: 2:00PM-3:00 PM

Weather: sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: The purpose of this inspection was to inspect the site and determine if any disturbance had been created, so the file can be closed as requested.

Inspection Summary: We inspected the site and it was determined that the site was never disturbed post law.

Conclusions and Recommendations: The site be closed.

Inspector's Signature Tom Munson

Date: 9/15/05

Directions to Site: The site is accessed by traveling West on Highway 21 out of Milford and after passing the San Francisco mountains, approximately two miles you turn north on a dirt road and travel along this road for 2 miles before you turn back East.

tm:jb

cc: Western Utah Copper
Attachment: Photos



5010060

CACTUS MINE DUMP
HISTORIC

DISTURBANCE CREATED
PRE-MINING LAW



5010060

HISTORIC PUMP
CACTUS



SO10060

CACTUS MINE PORTAL
HISTORIC
AREA WERE MINE
WAS TO BE ACCESSED
THERE IS WATER
DISCHARGING FROM
THE MINE.